

AWS-2850 Step II Static Reducer

Have you ever noticed that on certain substrates, such as Fiberglass or Plastic, and to a lesser degree Metal, after tacking there is a static charge left on that surface?

This static charge can cause us a problem with dirt in our paint job. The static acts like a magnet, drawing unwanted dust or lint into our wet paint.

Static can also cause us a problem with metallic control, especially on our blend edge. Static is not a Painter's friend!

Over the years Painters have used different methods to remove the static charge from the object being painted.

Some have used a chain wrapped around the frame, (hard to do with a Spoiler). Some used a spray, some used a Gun that did the job, some used alcohol wipes, and there are many other ways to get rid of that static.

Our AWS-2850 Static Reducer will also neutralize that troublesome static charge. The cloth is the same that is used for the Tack Cloth, treated with a different substance to accomplish the job. Both Cloths are user friendly over Waterborne Basecoats. Waterborne Basecoats are not friendly to contaminates.

If you want less dirt in your paint job, and better Metallic control, try our AWS-2850 Static Reducing Wipes. They are currently being used at the O.E.M. level.

Keep your cloth clean and dry. Just wipe and the static is gone!