



Tips on mixing Versaprime 2K Primer

If spraying through a 1.8 or smaller fluid tip, add 1 part of solvent.

It is not recommended to use a Fluid Tip smaller than 1.7

Example: Mixing ratio of Gray and Buff 4:1:1

Mixing ratio for Pre Tinted Primer 5:1:1

This primer levels out nicely, especially when using Superflow Solvents

At 75° use Moderate SuperFlow and at 85° use Hot Weather SuperFlow

If not using solvent, a larger tip can be used, up to a 2.2.

The primer will still level out nicely.

When mixing the Tintable Primer, remember to SHAKE or STIR the tints VERY WELL. They are very concentrated and must be dispersed before mixing with the primer. If this is not done, the primer will not be as rich in color as it should be.

Robert Coker

Technical Representative

Vogel Automotive Coatings

Cell # 606-304-1238